**Total No. of Questions : 8]** 

## P751

# [5870] - 1055

#### SEAT No. :

[Total No. of Pages : 2

### T.E. (Electrical)

## **COMPUTER AIDED DESIGN OF ELECTRICAL MACHINES** (2019 Pattern) (Semester -II) (303149)

*Time: 2<sup>1</sup>/<sub>2</sub> Hours]* Instructions to the candidates: [Max. Marks: 70

- Answers Q.1 or Q.2, Q.3 or Q.4, Q.5 or Q.6, Q.7 or Q.8 1)
- Figures to the right side indicate full marks. 2)
- Neat diagram must be drawn whenever necessary. 3)
- Assume suitable data, if necessary. *4*)
- *Q1*) a) Explain the procedure to estimate the no load current of three phase transformer. [6]
  - b) Calculate the percentage regulation at full load & 8pf lag for a 300kVA, 6600/440v, delta-star, 3 phase, 50H<sub>7</sub>, core type transformer having cylindrical coils of equal length with the following data. Height of coils=4.7 cm, thickness of HV coil=1.6 cm, thickness of LV coil=2.5 cm, insulation between LV&HV coils=1.4 cm, Mean diameter of the coils=27 cm, volt/ turns=7.9 V, full load copper loss=3.75Kw [8]
  - State & explain the measures to overcome the mechanical forces under c) short circuit conditions [4]
- Discuss mechanical forces developed under short circuit condition in a *Q2)* a) transformer. [6]

QR

- Draw and explain generalized flow chart for design of transformer. b)
- State the assumptions made while calculating leakage reactance of c) transformer. [6]
- Discuss the various factors to be considered for selection specific Q3) a) magnetic loading  $(B_{av})$  and specific electric loading (ac). [10]
  - What are the various types of AC windings for three phase induction b) motor? Explain in brief any two. [7]

#### OR

- Derive the output equation of a 3 phase induction motor in terms of its **04)** a) specific loadings. Also indicate the significance of terms involved. [7]
  - Estimate the main dimensions for 3 $\phi$ , 50Hz, 10kW, 400V, 4 pole squirrel **b**) cage induction motor. Assume full load efficiency of 0.85, full load power factor of 0.9 and winding factor 0.96. The specific magnetic loading is 0.6 wb/m<sup>2</sup> and the specific electric loading=22000A/m. Take rotor peripheral speed as 25 m/s at synchronous speed. [10]

*P.T.O.* 

- **05)** a) Explain the factors should be considered when estimating the length of air gap of three phase induction motor. Why the air gaps should be as Small as possible? [10]
  - Discuss the design of wound rotor w.r.t the following b) [8]
    - no. of rotor i)
    - ii) no.of rotor turr
    - iii) area of rotor conductors
    - rotor windings. iv)
- OR
- Discuss the various factors which decide selection of number of stator **06)** a) slots in case of 3 phase induction motor [8]
  - A 15KW, 36, 50Hz, 400V, 4 pole, star connected squirrel cage induction b) motor has 60 slots, each containing 7 conductors. The rotor slot's are 50. Assume full load efficiency as 0.85 full load Power factor as 0.9 and rotor mmf is 80% of stator mmf. Calculate the value of bar and end ring current. Also find the area of each bar and each end ring, if current density is 5A/mm<sup>2</sup> [10]
- Derive the equation for No Load Current of 36 induction motor. **Q**7) a) [10] a
  - Draw and explain generalized flow chart for design of three phase b) induction motor.
    - OR
- State and explain with neat sketches different types of leakage fluxes in **08)** a) an induction motor and estimate slot leakage reactance in an induction motor. [10]
  - Explain the effect of ducts on the calculation of magnetizing current of b) 3¢ induction motor. [7]

[5870] - 1055