Total No. of Questions : 4]		estions: 4]	<u>^</u>	SEAT No.:				
PE6				[Total	No. of Pages : 2			
		[6579]	306					
	T.F	E. (Mechanical/Automobi	le Engin	eering) (Inse	em)			
	\mathbf{N}	IACHINING SCIENCE A	AND TE	CHNOLOG	\mathbf{Y}			
(2019 Pattern) (Semester - I) (302045-B) (Elective-I)								
Time: 1				[.	Max. Marks: 30			
Instructi 1)		the candidates: Q.1 or Q.2 and Q.3 or Q.4.						
2)		abeled diagrams must be drawn w	vherver ned	cessarv.	·O			
<i>3</i>)		ne suitable data, notations if nece			(
<i>4</i>)	Figur	es to right indicate full marks.		73				
5)	Use of	f non-programmable electronic co	alculator is	allowed	າ"			
Q1) a)	Enu	merate the factors on which the	ne tool we	ar and tool life	depend. [5]			
b)	Con	npare between Continuous cl	hip and d	iscontinuous o	chip with four			
	. 01	erence points.	9, 3	2	[4]			
c)	Foll	lowing observations are noted	in orthog	onal cutting op	peration set up:			
ŕ			S	O	[6]			
	i)	Rake angle = 12°,	2					
	ii)	Cutting speed 80 m/min.						
	iii)	Chip thickness after metal cu	at = 0.80 r	nm,	C			
	iv)	Uncut chip thickness = 0.40	mm,					
	v)	Cutting force = 3000 N,						
	vi)	Thrust force = 1000 N.			. 5			
	Calo	culate:			'.O ₂ .			
	1)	Frictional force acting on chi	ip	3				
	2)	Coefficient of friction at tool	chip inte	rface)			
	3)	Shear angle	-	2 %				
	4)	Shear Force along shear plan	ne.					
	5)	Force normal to shear plane.						
	6)	Cutting power.	(2,7				
				<u> </u>				

Q^{2}	a)	Draw a neat sketch of "Chip Breaker" and Justify why it is needed? [5]	
	b)	Compare between orthogonal and oblique cutting. (Minimum Four Points)	
		[4]	
	c)	Using Taylor's equation and using $n = 0.5$, $C = 40$, calculate the	
		percentage increase in tool life when cutting speed V is reduced by 50%	
		[6]	h
Q 3)	a)	Illustrate with neat sketch any one method of the thread rolling process	
		for manufacturing of threads. Why rolled threaded parts are stronger	
		than machined threads? [6]	
	b)	What is gear hobbing? Explain with neat sketch gear hobbing process	
		[5]	
	c)	Explain with neat diagram any one method Multi Rio Thread grinding for	
		precision thread manufacturing [4]	
		OR	
<i>Q4</i>)	a)	Describe with neat sketch thread muling process. [6]	
	b)	Illustrate with neat sketch gear shaping process. [5]	
	c)	What is gear inspection? Explain the role of gear inspection in gear	
		manufacturing process. [4]	
		CO CO	
			^
			+
		8 1.5°	
	1	76.	
	1	306 2 P. Marian San Control of the State of	
(
[657	79]	306	