Total No	o. of Questions : 8] SEAT No. :
PD41	
	[6402]-111
	S.E. (Robotics & Automation Engineering)
INDU	STRIAL ELECTRONICS & ELECTRICAL TECHNOLOGY
	(2019 Pattern) (Semester - III) (211501)
	1/2 Hours] [Max. Marks : 70
	ions to the candidates:
1)	Solve Q.1 or Q.2, Q.3 or Q.4, Q.5 or Q.6, Q.7 or Q.8.
2)	Figures to the right indicate full marks.
3) 4)	Neat diagrams must be drawn wherever necesssary. Assume suitable additional data if necessary.
<i>5</i>)	Use of non-programmable calculator is allowed.
0)	ese whom programmable culculation is unto wear
Q1) a)	Explain following functions used in ADC [6]
	i) analogRead() function;
	ii) analogWrite() function;
	analogReference() function
b)	What is ADC? Write features of ADC in AtMega 328P microcontroller.[4]
c)	Draw and explain interfacing of strain gauge with Arduino Atmega 328P.
	Write its algorithm. [8]
	Θ R
Q2) a)	Draw and explain interfacing of LVDT with Arduino Atmega 328P. Write
	its algorithm. [8]
b)	
	Atmega 328P. Output of LM35 is connected to Arduino analog input pin
	number A2.
c)	Explain the concept of PWM with waveform. [6]
22)	
Q3) a)	Explain the following types of DC motors with the neat diagram. [6]
	i) DC Series Motor;
1 \	ii) DC Shunt motor.
b)	Explain construction of DC generator along with its neat diagram. [7]
c)	Draw and explain Torque – Armature current characteristics for DC series
	motor. [4]
	OR
Q 4) a)	Explain the armature resistance control method used for controlling the
	speed of the DC motor. Explain with neat diagram. What are the drawbacks of that method? [7]
b)	Derive the torque equation of DC motor. [6]
c)	Draw and explain Speed – Armature current characteristics for DC series
<i>C)</i>	motor. [4]
	9.
	P.T.O.

Q 5)	a)	The power input to the 550 V, 50 Hz, 6 pole, 3 phase induction motor running at 970 rpm is 45 kW. The stator losses are 1 kW and windag loss are 2 kW. Calculate	e
		i) Slip;	
		ii) Rotor copper loss;	j.
		iii) Efficiency of motor	
	b)	Explain power stages in three phase induction motor. [4	ij
	c)	Explain working, principle of three-phase induction motor along with th	
		neat diagram. [8	[]
Q6)	a)	What is the need of the starter? Explain the star-delta starter used to star	rt
		three phase induction motor, with the neat sketch. [8]	}]
	b)	Draw and explain Torque – slip characteristics for three phase inductio	n
		motor. [4	[]
	c)	A 6 pole, 50 Hz, 3-phase induction motor running at full load with 59	
		slip develops a torque of 155 N-m at the shaft. The friction and windag	
		losses are 250 W, and stator iron losses amounts to 1600W. Calculate[6	ני
		i) Output Power;	
		ii) Rotor Copper loss;	
		iii) Efficiency at full load.	
Q 7)	a)	Write down two applications of the following motors. [4	IJĆ
		i) Stepper motor;	5
		ii) BLDC motor.	
	b)	Draw neat sketch of Universal motor and explain its working. [6	6]
	c)	Explain construction and working of Linear Induction Motor with near	at
		sketch. [7	']
		OR	
Q 8)	a)	Compare AC series and DC series motor in detail. [4	[]
	b)	Draw the sketch of shaded pole induction motor and explain its working. [6]	6]
_^	c)	Explain the construction and working of the permanent magnet steppe	r
	1	motor with neat diagram. [7	']
4	/	6. V	